

# Invoice

Wholesale Electronics  
9101 W. SAHARA #105-D24  
Las Vegas, NV 89117  
702-739-5990


DATE	INVOICE #
2/28/2001	13289

## BILL TO

JOE AMARO  
333 COHANNET ST.  
TAUNTON, MA 02780

## SHIP TO

JOE AMARO  
333 COHANNET ST.  
TAUNTON, MA 02780  
508-880-0617  
508-942-4398 CELL

P.O. NUMBER	TERMS	REP	SHIP	VIA	F.O.B.	PROJECT
02780	RETURN	MC	2/28/2001	UPS 1 SAVER		
QUANTITY	ITEM CODE	DESCRIPTION			PRICE EACH	AMOUNT
7	VM4	VM4000 UNIVERSAL W/4 REM & 5 BOOKS			0.00	0.00
1	CB	COOL BOX W/O REM			0.00	0.00
4	VMR	VM 4000 REMOTE			10.00	40.00
	F	FREIGHT DIFF UPS GR TO UPS 1			69.00	69.00
						
Thank you for your business.					Total	\$109.00

All products carry a 30 day money back guarantee and a 1 year parts and labor warranty. If within 30 days of purchase you are not satisfied, you may return your order for refund or exchange (less S&H). No refunds after 30 days. All returned products must have prior return authorization (RA) approval and must be received within 14 days of obtaining the RA. All returned products must be complete, in un-tampered original condition, including all original boxes, components, manuals, paperwork, etc. and must include invoice showing the RA number assigned for the return. All merchandise ordered in error, returned without authorization, or returned incomplete, will be assessed a 25% restocking fee. All shipping, handling, and insurance fees are at customers expense. All returned merchandise must show a legible RA number on the shipping label. For technical support call

EVIDENCE # 2A PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date 3-9-01 Corp. # I-COMS  
 Account # 43747-04 Converter # 010101685  
 Name: Joe Amaro / Dimas Amaro Converter Type: VM 4000 Remote Cable  
Converter  
 Address: 333 Cohannet Street Received From: UPS pursuant to warrant on  
3/9/01  
 City: Taunton State/Zip Ma. 02780  
 SSN#: \_\_\_\_\_ Generated From: \_\_\_\_\_

## Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes  
 Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

Remote Cable Converter

## OUTSIDE CONVERTER APPEARANCE

P Security Tabs Missing  
I Outside Screws Missing  
R Converter Damaged  
A Marks Around Outside Screw  
T Wires Cut  
E Tampered Codes

## INSIDE CONVERTER APPEARANCE

U ADP Module Forced Open  
U ADP Module Cover Missing  
N Scratches/Marks on Key Chips  
I Jumper Wires Still In Place  
T Scratches/Marks on Legs of Key Chips  
 Missing Prom # \_\_\_\_\_

## 4 Point Test

Testing Point	Codes/Comments	Pass/Fail
1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2. Converter has 210 code or higher	<u>I</u>	<u>N</u>
3. Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4. Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

## FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT/

EVIDENCE # 2B PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	002703362
Name:	Joe Amaro / Dimas Amaro	Converter Type:	VM 4000 Remote Cable Converter
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

## Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

## CODES RECEIVED

## OTHER NOTABLE FEATURES

Remote Cable ConverterOUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>U</u>	ADP Module Cover Missing
<u>N</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 2C PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	003100799
Name:	Joe Amaro / Dimas Amaro	Converter Type:	VM 4000 Remote Cable Converter
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

## Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes

## Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

## OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

## INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

## 4 Point Test

Testing Point	Codes/Comments	Pass/Fail
1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2. Converter has 210 code or higher	<u>I</u>	<u>N</u>
3. Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4. Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

## FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT



EVIDENCE # 2D PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	6427153
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Coolbx / 3690
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

## Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
------------------	------------	----------------	------------

## Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

## OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

## INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

## 4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

## FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT/

ACCOUNT HISTORY SUMMARY

EVIDENCE # 2E PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010104514
Name:	Joe Amaro / Dimas Amaro	Converter Type:	VM 4000 Remote Cable Converter
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

## Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes

## Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>U</u>	ADP Module Cover Missing
<u>N</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

AT&T BROADBAND  
CONVERTER TEST FORM

EVIDENCE # 2F PACKAGE # 2

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010104512
Name:	Joe Amaro / Dimas Amaro	Converter Type:	VM 4000 Remote Cable Converter
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

## Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
------------------	------------	----------------	------------

## Pre 4 Point Test

## CODES RECEIVED

Instructions attached to owner's Manual : to Decode-push mem 2

## OTHER NOTABLE FEATURES

Button- to save this information, push the mem button above ft,  
then push the ft+ button within 3 secondsOUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

EVIDENCE # 2G PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date 3-9-01 Corp. # I-COMS  
 Account # 43747-04 Converter # 010101858  
 Name: Joe Amaro / Dimas Amaro Converter Type: VM 4000 Remote Cable  
Converter  
 Address: 333 Cohannet Street Received From: UPS pursuant to warrant on  
3/9/01  
 City: Taunton State/Zip Ma. 02780  
 SSN#: \_\_\_\_\_ Generated From: \_\_\_\_\_

## Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes

Pre 4 Point Test

## CODES RECEIVED

## OTHER NOTABLE FEATURES

## OUTSIDE CONVERTER APPEARANCE

P Security Tabs Missing  
I Outside Screws Missing  
R Converter Damaged  
A Marks Around Outside Screw  
T Wires Cut  
E Tampered Codes

## INSIDE CONVERTER APPEARANCE

U ADP Module Forced Open  
N ADP Module Cover Missing  
I Scratches/Marks on Key Chips  
T Jumper Wires Still In Place  
T Scratches/Marks on Legs of Key Chips  
Missing Prom #

## 4 Point Test

Testing Point	Codes/Comments	Pass/Fail
1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2. Converter has 210 code or higher	<u>I</u>	<u>N</u>
3. Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4. Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

## FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT



EVIDENCE # 2H PACKAGE # 2

AT&T BROADBAND  
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	8551980
Name:	Joe Amaro / Dimas Amaro	Converter Type:	Coolbx 3690
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

## Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

## CODES RECEIVED

## OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>U</u>	ADP Module Cover Missing
<u>N</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY